

Dry Shed 4 Photos (2017)



South east Corner



South Side of Building





North Side of Building



East Side of Building





West side of Building



Collapsed Wall Northeast Side of Shed



Hole in roof Southwest





Hole in roof, interior shot



Hole in wall, interior shot





South east bay looking north, illustrates wall framing/CMU, roof structural system and asphalt floors



North East Bay looking south and west





Typical deteriorated paint on external walls



Deteriorated sprinkler main





Raven nest



Typical vegetation surrounding shed