



Imagery ©2019 Google, Map data ©2019 50 ft



\* This is a picture of the proposed fence with an added access gate on the East Side of the property on Harbor Avenue.



Split Rail Fence Design  
materials: redwood/Cedar/Doug Fir