Attachment 2: Dry Shed 4 Photos (2017)

South east Corner

South Side of Building

North Side of Building

East Side of Building

West side of Building

Collapsed Wall Northeast Side of Shed

Hole in roof Southwest

Hole in roof, interior shot

Hole in wall, interior shot

South east bay looking north, illustrates wall framing/CMU, roof structural system and asphalt floors

North East Bay looking south and west

Typical deteriorated paint on external walls

Deteriorated sprinkler main

Raven nest

Typical vegetation surrounding shed